

Drone Inspection Report

Severity: HIGH

Detections:

person - 0.3

Defects:

1 possible cracks detected

Alerts:

Crack detected — inspection required

Inspection Image:

