

Drone Inspection Report

Severity: HIGH

Detections:

Defects:

1 possible cracks detected

Alerts:

Crack detected — structural inspection required

Inspection Image:

