M

Product Description:	**Men Crew Neck 100% Cotton Polo T-Shirt**			**Inspection Team:**
Report No.:	**FI_MPSS_0011**	**Agency:**	**MPSS Agency**	**Item / Style No.:**
Customer:	**CAGI**	**Factory Name:**	**JRP EXPORTS**	**Order Quantity:**
Account:	**MENS**	**Factory Location:**	**SEYENTHAMPALAYAM**	**Purchase Order No.:**
Merchandiser:	**John Doe (QA Auditor)**	**Country of Origin:**	**INDIA**	**Program / Season Nam**
[X] Knitted	[ ] Woven	[ ] Sets	Color Ways:	WHITE
[X] Adults	[ ] Boys	[ ] Girls	Size:	M,L,XL

Type of Sample	Type of Inspection	Type of Order	Total Cartons	Ship by
Fit / Size Set Sample	**1st Batch | Pre-Final**	**Replenishment**	**Total: 53**	**Sea [X]**
Pre-Production Sample	**In-line [X] | Final [X]**	**New Order [X]**	**Ship: 53**	**Air [ ]**
TOP Sample	**Re-Inline | Re-Final**		**Opened: 14**	
Reference Sample				

ANSI ASQ Z1.4 – 2003 AQL SAMPLING PLAN				
AQL Critical: 0 | Major	Level II [X]	Inspected Qty: 125	Critical Accept / Rejec	0
			Major Accept / Reject	7 / 8
			Minor Accept / Reject	10 / 11
			Total Critical Defect:	0
			Total Major Defect:	2
			Total Minor Defect:	3

Items to Check

1	**Approved Prod Spec - BOM**	**YES [X]**
2	**Main & Care Label**	**YES [X]**
3	**Carton Label Placement**	**YES [X]**
4	**Carton Label Barcode Printable & Scannable**	**YES [X]**
5	**Wide Goods per Approved**	**YES [X]**
6	**Trims - Components per Approved**	**YES [X]**
7	**Fabric Weight**	**YES [X]**
8	**TOP Samples Pulled Out from the Bulk**	**YES [X]**
9	**Fabric Color**	**YES [X]**
10	**Moisture Level Test**	**YES [X]**
11	**Metal Detection Check**	**YES [X]**
12	**Packing Method**	**YES [X]**
13	**Hanging Method**	**YES [X]**
14	**Correct Carton Used**	**YES [X]**
15	**Cartons Too Empty / Overloaded / Damaged**	**YES [X]**
16	**UPC / Barcode**	**YES [X]**
17	**Hang / Collar Tags**	**YES [X]**
18	**Draw String Review**	**YES [X]**
19	**Sharp Points & Sharp Edges**	**YES [X]**

20	**Small Parts**	**YES [X]**
21	**Smell Check**	**YES [X]**
22	**Lab Test Report**	**YES [X]**

y Profile Sourcing Solutions

Final Inspection Report

My Profile Sourcing Solutions	**Inspection Date:**	2026-10-14
YCAT0110		
2600		
4500159665		
SUMMER		

PO No.	PO Qty	Qty Ship	Qty Insp	Destination
4500159665	2600	2600	125	USA
TOTAL	2600			

PASSED: [ ]	No critical defects found during visual and packing inspection. Order conforms to AQL 2.5 standards.		
FAILED: [ ]			
PENDING: [X]			
NEED IMPROVEMEN			

Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample

Conforms to approved standard sample
Conforms to approved standard sample
Conforms to approved standard sample