



CAR INSPECTION
EXPERT

PDI (New Car Inspection) Report

ID: qw

Assigned Expert Name: jhg

Customer Name: mknjbh

Generated: 2025-12-07 18:39:50

STEP 1 — CAR INSPECTION

Booking ID: qw

Assigned Expert Name: jhg

Inspection Expert City: kjh

Customer Name: mknjbh

Date: 1111-11-11

Time: 11:01

Inspection Address: njbhv

OBD Scanning: Yes

STEP 2 — EXPERT DETAILS

Inspection 45 Minutes Delayed?: No

Date: 06-12-2025

Time: 08:10 PM

Latitude: 31.244753

Longitude: 75.702245

Location Address: Phagwara Tahsil, ੧੪੪੪੧੧, Punjab, 144411, India

Photo with Car Number Plate



STEP 3 — CAR DETAILS

Car Company: fdsgdhgfh

Car Variant: adfsgfh

Car Registered State: sadfdsgdh

Car Registered City: asdfd

Car Color: dsdf

Car KM Current Reading: fdsfd

Number of Car Keys Available: 23

Chassis Number: 2132

Engine Number: 234

Car KM Reading Photo



Chassis No. Plate



STEP 4 — CAR DOCUMENTS

Vehicle Insurance: Not Available

Form 22: Available

Form 21: Not Available

Registration Certificate: Available

Road Tax Receipt: Not Available

Warranty Card: Available

Owner's Manual: Not Available

Service Booklet: Available

Bank finance NOC: Not Available

Extended warranty: Available

Accessories Invoice: Not Available

STEP 5 — EXTERIOR BODY

Driver Front Door: Ok

Driver - Front Fender: Ok

Driver - Front Door Window: Ok

Driver - Side View Mirror Housing: Ok

Driver - Side View Mirror Glass: Ok

Driver - Indicator Front: Ok

Driver - Front Wheel Arch/ Fender Lining: Ok

Driver - Front Mud Flap: Ok

Driver - Front Cladding: Ok

Driver - Roof Rail: Ok

Driver - Door Sill: Ok

Driver -Back Door: Ok

Driver - Back Door Window: Ok

Driver - Rear Cladding: Ok

Driver - Rear Wheel Arch / Fender Lining: Ok

Driver - Back Mud Flap: Ok

Driver - Back Quarter Panel: Ok

Driver - Back Indicated: Ok

Passenger - Back Indicated: Ok

Rear Windshield: Ok

Connected Taillights: Ok

Driver Taillights: Ok

Passenger Taillights: Ok

Rear Number Plate: Ok

Front Bumper: Repainted, Minor Scratches, Major Scratches, Minor Dents, Major Dents, Damaged, Replaced, Panel Gaps

Front Bumper Image



Rear Bumper: Ok

Boot Space Door/ Backdoor: Ok

Passenger - Back Door: Ok

Passenger - Back Door Window: Ok

Passenger - Rear Cladding: Damaged, Scratches, Not Applicable

Passenger - Rear Cladding Image



Passenger - Rear Wheel Arch / Fender Lining: Damaged, Rusted

Passenger - Rear Wheel Arch / Fender Lining Image



Passenger - Back Mud flap: Damaged, Not Available

Passenger - Back Mud flap Image



Charger Flap: Ok

Passenger Door Sill: Ok

Passenger Back Quarter Panel: Ok

Passenger - Roof Rail: Damaged, Not Available

Passenger - Roof Rail Image



Passenger Front Door: Ok

Passenger Front Door Window: Ok

Passenger Side View Mirror Housing: Ok

Passenger Side View Mirror Glass: Ok

Passenger Front Indicator: Ok

Passenger Front Fender: Ok

Passenger - Front Wheel Arch / Fender Lining: Damaged, Rusted

Passenger - Front Wheel Arch / Fender Lining Image



Passenger - Front Mud flap: Damaged, Not Available

Passenger - Front Mud flap Image



Passenger - Front Cladding: Damaged, Scratches, Not Applicable

Passenger - Front Cladding Image



Windshields: Ok

Match all Glasses Serial Number: Not Matching

Match Glasses Serial Number Remark: YESS 100

Front Bonnet Top: Ok

Front Grill: Ok

Fog Light's: Ok

Driver Headlight: Ok

Passenger Headlight: Ok

Front Number Plate: Ok

Car Roof Outside: Ok

STEP 6 — BATTERY, CHARGER AND HOOD

Charger Output (KilloWatts): 123

Charger: Not Working

Charger Port: Damaged

Battery Charging on Connecting Charger: Not Able to Check

Motor Coolant Level: Ok

Motor: Not Ok

Abnormal Motor Noise: Present

Motor Manufacturing Date: 1200-11-11

Cables: Not Ok

Fuse Box: Not Ok

Auxilliary Battery: Ok

Charger Photo



Charger Port Photo



STEP 7 — BODY FRAME ACCIDENTAL CHECKLIST

Radiator Core Support: Rusted

Radiator Core Support Remark: aaa

Radiator Core Support Image



Match Chassis No Plate with the Real Body: Not Matching

Match Chassis No Plate with the Real Body Remark: aaa

Match Chassis No Plate with the Real Body Image



Driver side Strut Tower Apron: Accidental, Rusted

Driver side Strut Tower Apron Remark: aaa

Driver side Strut Tower Apron Image



Passenger Strut Tower Apron: Accidental, Rusted

Passenger Strut Tower Apron Remark: aaa

Passenger Strut Tower Apron Image



Driver side Front Rail: Accidental, Rusted

Driver side Front Rail Remark: aaa

Driver side Front Rail Image



Passenger Side Front Rail: Accidental, Rusted

Passenger Side Front Rail Remark: knjb

Passenger Side Front Rail Image



Front Bonnet UnderBody: Rusted, Scratches

Front Bonnet UnderBody Remark: aaa

Front Bonnet UnderBody Image



Driver Side A Pillar: Repainted

Driver Side A Pillar Remark: aaa

Driver Side A Pillar Image



Driver Side B Pillar: Accidental, Rusted, Repainted

Driver Side B Pillar Remark: aaa

Driver Side B Pillar Image



Driver Side C Pillar: Rusted

Driver Side C Pillar Remark: aaa

Driver Side C Pillar Image



Driver Side D Pillar: Accidental

Driver Side D Pillar Remark: aaa

Driver Side D Pillar Image



Driver Side Running Board: Accidental

Driver Side Running Board Remark: aaa

Driver Side Running Board Image



Boot Lock Pillar: Accidental, Rusted

Boot Lock Pillar Remark: jhg

Boot Lock Pillar Image



Boot Floor: Rusted, Scratches

Boot Floor Remark: kjhbgc

Boot Floor Image



Rear Sub Frame / Z Axle: Scratches, Repainted, Rusted

Rear Sub Frame / Z Axle Remark: jhgc

Rear Sub Frame / Z Axle Image



Passenger Side D Pillar: ok

Passenger Side D Pillar Image



Passenger Side C Pillar: ok

Passenger Side C Pillar Image



Passenger Side B Pillar: ok

Passenger Side B Pillar Image



Passenger Side A Pillar: ok

Passenger Side A Pillar Image



Passenger Side Running Board: ok

Passenger Side Running Board Image



STEP 8 — ELECTRICAL AND INTERIOR

Central Lock Working: Ok

Ignition Switch / Push Button: Not Ok

Driver - Front Indicator: Working

Passenger - Front Indicator: Not Working

Driver Headlight: Working

Passenger Headlight: Not Working

Driver Headlight Highbeam: Working

Passenger Headlight Highbeam: Not Working

Front Number Plate Light: Working

Driver Back Indicator: Not Working

Passenger Back Indicator: Not Working

Back Number Plate Light: Working

Brake Light Driver: Not Working

Brake Light Passenger: Working

Driver Tail Light: Working

Passenger Tail Light: Not Working

Steering Wheel Condition: Not Ok

Steering Mountain Controls: Working

Back Camera: Not Working

Reverse Parking Sensor: Working

Multi Function Display: Working

Multi Function Display (Car On)



Multi Function Display (Car Start)



Car Horn: Not Working

Entertainment System: Working

Cruise Control: Not Working

Interior Lights: Not Working

Sun Roof: Not Applicable

Bonnet Release Operation: Not Working

Charging Port Cap Release Operation: Not Applicable

Window Safety Lock: Not Working

Driver ORVM Controls: Ok

Passenger ORVM Controls: Not Ok

Glove Box: Not Ok

Wiper: Ok

Rear View Mirror: Not Ok

Dashboard Condition: Ok

Car Roof From Inside: Ok

Car Roof From Inside Image



Seat Adjustment Driver Side: Working

Front Driver Side Seat Condition: Not Ok

Front Driver Side Floor: Covered - Not Able To See

Front Driver Side Seat Belt: Not Ok

Front Passenger Side Seat Condition: Not Ok

Front Passenger Side Floor: Not Ok

Front Passenger Side Seat Belt: Ok

Seat Adjustment Passenger Side: Not Working

Window Driver Side: Working

Window Passenger Rear Side: Not Working

Window Driver Rear Side: Working

Seat Adjustment Driver Rear Side: Not Working

Back Driver Side Floor: Not Ok

Back Driver Side Seat Belt: Not Ok

Back Driver Side Seat Condition: Ok

Back Passenger Side Floor: Not Ok

Back Passenger Side Seat Condition: Ok

Back Passenger Side Seat Belt: Not Ok

Child Safety Lock: Working

Window Passenger Side: Not Working

Seat Adjustment Passenger Rear Side: Not Working

Check All Buttons: Yes

STEP 9 — WARNING LIGHTS

Charging System Warning: Present

Power Steering Problem: Not Present

ABS Sensor Problem: Not Present

Airbag Sensor Problem: Not Present

Battery Problem: Present

Low Coolant / Overheating: Not Present

Brake System Warning: Present

Any Other Lights Found?: Not Present

STEP 10 — AIR CONDITIONING

Air Conditioning Turning On: Not Ok

AC Cool Temperature: 1C

AC Hot Temperature: 10C

Air Condition Direction Mode Working: Not Ok

De Fogger Front Vent Working: Ok

De Fogger rear Vent Working: Not Ok

Air Conditioning All Vents: Not Ok

AC Abnormal Vibration: Present

Air Condition Image at Fan Max Speed



STEP 11 — BRAKES & STEERING

Brake Pedal: Not Ok

Steering Rotating Smoothly: Ok

Steering Coming Back While Driving: Not Ok

Steering Weird Noise: Present

Alignment: Not Ok

Bubbling: Present

Steering Vibration: Not Present

STEP 12 — AXLE

Left Axle: Not Ok

Right Axle: Ok

Abnormal Noise: Not Present

STEP 13 — TYRES

Tyre Size: adfs

Tyre Type: With Tube

Rim Type: Alloy

Driver Front Tyre Depth Check: Good

Driver Front Tyre Manufacturing Date: asd

Driver Front Tyre Shape: Damaged

Driver Back Tyre Depth Check: Average

Driver Back Tyre Manufacturing Date: ads

Driver Back Tyre Shape: Damaged

Passenger Back Tyre Depth Check: Average

Passenger Back Tyre Shape: Damaged

Passenger Front Tyre Depth Check: Bad

Passenger Front Tyre Manufacturing Date: sa

Passenger Front Tyre Shape: Damaged

Stepney Tyre Depth Check: Average

Stepney Tyre Manufacturing Date: asfd

Stepney Front Tyre Shape: Damaged

Sign of Camber Issue: Not Present

Driver Front Tyre Tread Depth



Driver Back Tyre Tread Depth



Passenger Back Tyre Tread Depth



Passenger Front Tyre Tread Depth



Stepney Tyre Tread Depth



STEP 14 — BRAKES

Brake Pads Front Driver Side: Not Ok

Brake Discs Front Driver Side: Not Applicable

Brake Calipers Front Driver Side: Not Able To Check

Brake Pads Front Passenger Side: Not Applicable

Brake Discs Front Passenger Side: Ok

Brake Calipers Front Passenger Side: Not Ok

Brake Pads Back Passenger Side: Ok

Brake Discs Back Passenger Side: Not Applicable

Brake Calipers Back Passenger Side: Not Ok

Brake Pads Back Driver Side: Not Applicable

Brake Discs Back Driver Side: Not Ok

Brake Calipers Back Driver Side: Not Ok

Brake Fluid Reservoir: Ok

Brake Fluid Cap: Not Ok

Parking Hand Brake: Ok

STEP 15 — SUSPENSION

Car Height: Not Ok

Shocker Bounce Test: Ok

Driver Side Suspension Assembly: Not Ok

Passenger Side Suspension Assembly: Ok

Passenger Side Shocker Leakage: Not Present

Driver Side Shocker Leakage: Present

STEP 16 — UNDER BODY

Driver Side Body Chasis: Not Ok, Not able to check

Passenger Side Body Chasis: Accidental, Not able to check

Rear Subframe: Not Ok, Rusted, Accidental, Not able to check

Front Protection Cover: Not Selected

Underbody Cables: Not Selected

Rear Protection Cover: Not Selected

Any Fuel Leaks under Body: Present

Underbody Left



Underbody Rear



Underbody Front



Underbody Right



STEP 17 — EQUIPMENTS

Tool Kit: Present

Tool Kit Image



STEP 18 — CAR IMAGES

Front



Back



Driver Side



Passenger Side



Front Dashboard



STEP 19 — FINAL RESULT

Any Issues Found in Car: asds

STEP 20 — PAYMENT TAKING

Payment: Yes

Payment Type: Online

Amount Paid: 123

Payment Proof



Car Inspection Expert System

This report contains complete inspection data from all 19 steps.

Report generated on 2025-12-07 18:39:52