



CAR INSPECTION
EXPERT

PDI (New Car Inspection) Report

ID: 12

Inspection Expert ID: N/A

Customer Name: asd

Generated: 2025-12-05 00:18:13

STEP 1 — CAR INSPECTION

Booking ID: 12

Assigned Expert Name: sad

Inspection Expert City: Mumbai

Customer Name: asd

Customer Phone Number: asd

Date: 0012-12-12

Time: 12:12

Inspection Address: 12

OBD Scanning: Yes

STEP 2 — PAYMENT TAKING

Payment: Yes

Payment Type: Online

Amount Paid: 12

Payment Proof



STEP 3 — EXPERT DETAILS

Inspection 45 Minutes Delayed?: Yes

Your Photo with car number plate



STEP 4 — CAR IMAGES

Front



Back



Driver Side



Passenger Side



Front Dashboard



STEP 5 — CAR DETAILS

Car Company: asd

Car Variant: asdasa

Car Registered State: asd

Car Registered City: 123

Fuel Type: Petrol

Engine Capacity (in CC): 123

Transmission Type: Manual

Car Color: asd

Car KM Current Reading: asd

Number of Car Keys Available: 12

Chassis Number: adsdfds

Engine Number: sads

Car KM Reading Photo



Chassis No. Plate



STEP 6 — EXTERIOR BODY

Driver Front Door: Repainted, Minor Scratches, Minor Dent's, Replaced, Not Opening Comfortably

Driver Front Door Image



Driver - Front Fender: Major Dent's, Minor Scratches, Rusted, Major Scratches, Minor Dent's

Driver - Front Fender Image



Driver - Front Door Window: Ok

Driver - Side View Mirror Housing: Ok

Driver - Side View Mirror Glass: Ok

Driver - Indicator Front: Ok

Driver - Front Wheel Arch/ Fender Lining: Ok

Driver - Front Mud Flap: Ok

Driver - Front Cladding: Ok

Driver - Roof Rail: Ok

Driver - Door Sill: Ok

Driver -Back Door: Ok

Driver - Back Door Window: Ok

Driver - Rear Cladding: Ok

Driver - Rear Wheel Arch / Fender Lining: Ok

Driver - Back Mud Flap: Ok

Driver - Back Quarter Panel: Ok

Driver - Back Indicated: Ok

Passenger - Back Indicated: Ok

Rear Windshield: Ok

Connected Taillights: Ok

Driver Taillights: Ok

Passenger Taillights: Ok

Rear Number Plate: Ok

Rear Bumper: Ok

Boot Space Door/ Backdoor: Ok

Passenger - Back Door: Ok

Passenger - Back Door Window: Ok

Fuel Filter Flap: Ok

Passenger Door Sill: Ok

Passenger Back Quarter Panel: Ok

Passenger Front Door: Ok

Passenger Front Door Window: Ok

Passenger Side View Mirror Housing: Ok

Passenger Side View Mirror Glass: Ok

Passenger Front Indicator: Ok

Passenger Front Fender: Ok

Windshields: Ok

Match all Glasses Serial Number: Matching

Front Bonnet Top: Ok

Front Grill: Ok

Fog Light's: Ok

Driver Headlight: Ok

Passenger Headlight: Ok

Front Number Plate: Damage

Front Number Plate Image



Car Roof Outside: Ok

STEP 7 — OBD SCAN

Any Fault Code Present: Port Not Working

OBD Scan Photo



STEP 8 — ELECTRICAL AND INTERIOR

Central Lock Working: Ok

Ignition Switch / Push Button: Not Ok

Driver - Front Indicator: Working

Passenger - Front Indicator: Not Working

Driver Headlight: Working

Passenger Headlight: Not Working

Driver Headlight Highbeam: Not Working

Passenger Headlight Highbeam: Working

Front Number Plate Light: Not Available

Driver Back Indicator: Not Working

Passenger Back Indicator: Working

Back Number Plate Light: Not Working

Brake Light Driver: Working

Brake Light Passenger: Not Working

Driver Tail Light: Working

Passenger Tail Light: Not Working

Steering Wheel Condition: OK

Steering Mountain Controls: Not Working

Back Camera: Working

Reverse Parking Sensor: Working

Car Horn: Not Working

Entertainment System: Not Applicable

Cruise Control: Not Working

Interior Lights: Not Working

Sun Roof: Working

Bonnet Release Operation: Not Working

Fuel Cap Release Operation: Not Working

Check Onboard Computer ADBLue Level- Diesel Cars: Working

Window Safety Lock: Not Working

Driver ORVM Controls: Ok

Passenger ORVM Controls: Not Ok

Glove Box: Ok

Wiper: Not Ok

Rear View Mirror: Ok

Dashboard Condition: Not Ok

Window Passenger Side: Working

Seat Adjustment Passenger Rear Side: Not Working

Check All Buttons: 100AB

STEP 9 — AIR CONDITIONING

Air Conditioning Turning On: Not Ok

Air Condition Direction Mode Working: Not Ok

De Fogger Front Vent Working: Ok

De Fogger rear Vent Working: Not Ok

Air Conditioning All Vents: Ok

AC Abnormal Vibration: Not Present

Air Condition Image at Fan Max Speed



STEP 10 — TYRES

Tyre Size: 1

Tyre Type: With Tube

Rim Type: Normal

Driver Front Tyre Depth Check: Average

Driver Front Tyre Shape: Damaged

Driver Back Tyre Depth Check: Good

Driver Back Tyre Shape: Damaged

Passenger Back Tyre Depth Check: Good

Passenger Back Tyre Shape: Damaged

Passenger Front Tyre Depth Check: Bad

Passenger Front Tyre Shape: Damaged

Stepney Tyre Depth Check: Good

Stepney Front Tyre Shape: Damaged

Sign of Camber Issue: Present

Driver Front Tyre Tread Depth



Driver Back Tyre Tread Depth



Passenger Back Tyre Tread Depth



Passenger Front Tyre Tread Depth



Stepney Tyre Tread Depth



STEP 11 — UNDER BODY

Any Fuel Leaks under Body: Present

Underbody Left



Underbody Rear



Underbody Front



Underbody Right



STEP 12 — EQUIPMENT'S

Tool Kit: Present

Tool Kit Image



STEP 13 — FINAL RESULT

Any Issues Found in Car: cpu -> keyboard

no keyboard =/ mouse

mouse == cpu

Photo of Issues



Car Inspection Expert System

This report contains complete inspection data from all 13 steps.

Report generated on 2025-12-05 00:18:15