



CAR INSPECTION
EXPERT

PDI (New Car Inspection) Report

ID: dsasfd

Engineer Name: asdfs

Customer Name: dafsfd

Generated: 2025-12-08 13:36:18

STEP 1 — CAR INSPECTION

Booking ID: dsasfd

Engineer Name: asdfs

Inspection Expert City: dads

Customer Name: dafsfd

Date: 1111-11-11

Time: 11:11

Latitude: 31.244753

Longitude: 75.702245

Location Address: Phagwara Tahsil, ☐☐☐☐☐☐, Punjab, 144411, India

OBD Scanning: Yes

STEP 2 — PAYMENT TAKING

Payment: Yes

Payment Type: Online

Payment Proof



STEP 3 — CAR IMAGES

Front

Back

Driver Side

Passenger Side

Front Dashboard

STEP 4 — ENGINE

Car Start: Not Ok

Wiring: Original Wiring Changed

Engine Condition: Not Ok

Engine Condition Image



Engine Noise: Not Ok

Engine Noise Image



Engine Oil: Not Ok

Engine Oil Image



Engine Oil Leakage: Not Ok

Engine Oil Leakage Image



Engine Oil Quality: Low Level

Engine Oil Cap: Sludge Present

Smoke from dipstick point: Present

Back Compression: Not Ok

Back Compression Image



Engine Mounting and Components: Not Ok

AC Compressor Mounting: Ok

Engine Vibration: Present

Hoses: Not Ok

Coolant: Not Ok

Coolant Image



Brake Oil: Not Ok

Brake Oil Image



Battery: Damaged

Battery Image



Transmission oil leakage: Not Present

AC Fan Belt: Ok

Engine Fan Belt: Not Ok

Radiator fan: Working

Radiator Condition: Not Ok

Exhaust Pipe: Black Particles Present

Exhaust Sound: Not Present

Smoke Emission: Ok

STEP 5 — CAR DETAILS

Car Company: Not Selected

Car Variant: Not Selected

Car Registered State: Not Selected

Fuel Type: Petrol, Diesel, Electric, Hybrid

Engine Capacity (in CC): Not Selected

Transmission Type: Not Selected

Car Color: Not Selected


Car KM Current Reading: Not Selected

Number of Car Keys Available: Not Selected

Chassis Number: Not Selected

Engine Number: Not Selected

Car KM Reading	Chassis No. Plate
Photo	



STEP 6 — EXTERIOR BODY

Driver Front Door: **Not Selected**

Driver - Front Fender: **Not Selected**

Driver - Front Door Window: **Not Selected**

Driver - Side View Mirror Housing: **Not Selected**

Driver - Side View Mirror Glass: **Not Selected**

Driver - Indicator Front: **Not Selected**

Driver - Roof Rail: **Not Selected**

Driver - Door Sill: **Not Selected**

Driver -Back Door: **Not Selected**

Driver - Back Door Window: **Not Selected**

Driver - Back Quarter Panel: **Not Selected**

Driver - Back Indicated: **Not Selected**

Passenger - Back Indicated: **Not Selected**

Rear Windshield: **Not Selected**

Connected Taillights: **Not Selected**

Driver Taillights: **Not Selected**

Passenger Taillights: **Not Selected**

Rear Number Plate: **Not Selected**

Rear Bumper: **Not Selected**

Boot Space Door/ Backdoor: **Not Selected**

Passenger - Back Door: **Not Selected**

Passenger - Back Door Window: **Not Selected**

Fuel Filter Flap: **Not Selected**

Passenger Door Sill: **Not Selected**

Passenger Back Quarter Panel: **Not Selected**

Passenger Front Door: **Not Selected**

Passenger Front Door Window: **Not Selected**

Passenger Side View Mirror Housing: **Not Selected**

Passenger Side View Mirror Glass: **Not Selected**

Passenger Front Indicator: **Not Selected**

Passenger Front Fender: **Not Selected**

Windshields: **Not Selected**

Match all Glasses Serial Number: **Not Selected**

Front Bonnet Top: **Not Selected**

Front Grill: **Not Selected**

Fog Light's: **Not Selected**

Driver Headlight: **Not Selected**

Passenger Headlight: **Not Selected**

Front Number Plate: **Not Selected**

Car Roof Outside: **Not Selected**

STEP 7 — OBD SCAN

Any Fault Code Present: Port Not Working

OBD Scan Photo



STEP 8 — ELECTRICAL AND INTERIOR

Central Lock Working: **Not Selected**

Ignition Switch / Push Button: **Not Selected**

Driver - Front Indicator: **Not Selected**

Passenger - Front Indicator: **Not Selected**

Driver Headlight: **Not Selected**

Passenger Headlight: **Not Selected**

Driver Headlight Highbeam: **Not Selected**

Passenger Headlight Highbeam: **Not Selected**

Front Number Plate Light: **Not Selected**

Driver Back Indicator: **Not Selected**

Passenger Back Indicator: **Not Selected**

Back Number Plate Light: **Not Selected**

Brake Light Driver: **Not Selected**

Brake Light Passenger: **Not Selected**

Driver Tail Light: **Not Selected**

Passenger Tail Light: **Not Selected**

Steering Wheel Condition: **Not Selected**

Steering Mountain Controls: **Not Selected**

Back Camera: **Not Selected**

Reverse Parking Sensor: **Not Selected**

Car Horn: **Not Selected**

Entertainment System: **Not Selected**

Cruise Control: **Not Selected**

Interior Lights: **Not Selected**

Sun Roof: **Not Selected**

Bonnet Release Operation: **Not Selected**

Fuel Cap Release Operation: **Not Selected**

Check Onboard Computer ADBLue Level- Diesel Cars: **Not Selected**

Window Safety Lock: **Not Selected**

Driver ORVM Controls: **Not Selected**

Passenger ORVM Controls: **Not Selected**

Glove Box: **Not Selected**

Wiper: **Not Selected**

Rear View Mirror: **Not Selected**

Dashboard Condition: **Not Selected**

Window Passenger Side: **Not Selected**

Seat Adjustment Passenger Rear Side: **Not Selected**

STEP 9 — AIR CONDITIONING

Air Conditioning Turning On: **Not Selected**

AC Cool



AC Hot



Air Condition Direction Mode Working: **Not Selected**

De Fogger Front Vent Working: **Not Selected**

De Fogger rear Vent Working: **Not Selected**

Air Conditioning All Vents: **Not Selected**

AC Abnormal Vibration: **Not Selected**

STEP 10 — TYRES

Tyre Size: **Not Selected**

Tyre Type: **Not Selected**

Rim Type: **Not Selected**

Driver Front Tyre Depth Check: **Not Selected**

Driver Front Tyre Shape: **Not Selected**

Driver Back Tyre Depth Check: **Not Selected**

Driver Back Tyre Shape: **Not Selected**

Passenger Back Tyre Depth Check: **Not Selected**

Passenger Back Tyre Shape: **Not Selected**

Passenger Front Tyre Depth Check: **Not Selected**

Passenger Front Tyre Shape: **Not Selected**

Stepney Tyre Depth Check: **Not Selected**

Stepney Front Tyre Shape: **Not Selected**

Sign of Camber Issue: **Not Selected**

Driver Front Tyre Tread Depth	Driver Back Tyre Tread Depth	Passenger Back Tyre Tread Depth
Passenger Front Tyre Tread Depth	Stepney Tyre Tread Depth	

STEP 11 — UNDER BODY

Any Fuel Leaks under Body: Present

Fuel Leaks Image



Underbody Left

Underbody Rear

Underbody Front

Underbody Right

STEP 12 — EQUIPMENT'S

Tool Kit: **Not Selected**

STEP 13 — FINAL RESULT

Any Issues Found in Car: aaaa

Issue Photo 2



Issue Photo 4



Car Inspection Expert System

⚠️ IMPORTANT NOTE:

While inspecting the vehicle, our boy will be responsible as long as he is at the inspection site, after that he will not be responsible even if anything happens to the vehicle.

Report generated on 2025-12-08 13:36:21