AwanSolveAi

Warranty Claim Cover Sheet

General heavy-equipment synthetic claim form

Field	Value
Claim ID	DEMO-004
Equipment	Excavator
Model	AX220
Serial	EXC-220-1042
Operating Hours	4286
Claim Date	2026-09-07

Customer Complaint

Boom drifts downward during hold.

Failure / Fault Code

HYD-P22

Claimed Cause

Hydraulic fault

Correction

Resealed boom cylinder

Claimed Part

SK-20491

Claimed Labor

6.5 h

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD