AwanSolveAi

Warranty Claim Cover Sheet

General heavy-equipment synthetic claim form

Field	Value
Claim ID	DEMO-008
Equipment	Generator
Model	DG175
Serial	GEN-175-22891
Operating Hours	4172
Claim Date	2026-09-11

Customer Complaint

Generator cranks but does not start.

Failure / Fault Code

143

Claimed Cause

Failed fuel pressure sensor

Correction

Replaced fuel pressure sensor

Claimed Part

FPS-2118

Claimed Labor

2.5 h

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD