AwanSolveAi

Diagnostic and Post-Repair Verification

Synthetic diagnostic/test record

Field	Value
Claim ID	DEMO-008
Model	DG175
Serial	GEN-175-22891
Test Date	2026-09-09
Verification Date	2026-09-10

Diagnostic Test

Fuel rail pressure

Measured Result

235 kPa

Fault Code

143

Post-Repair Verification

NOT DOCUMENTED

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD