AwanSolveAi

Diagnostic and Post-Repair Verification

Synthetic diagnostic/test record

Field	Value
Claim ID	DEMO-009
Model	DG175
Serial	GEN-175-22891
Test Date	2026-09-10
Verification Date	2026-09-11

Diagnostic Test

Fuel rail pressure

Measured Result

235 kPa

Fault Code

143

Post-Repair Verification

Load test PASS at 75% rated load for 30 minutes.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD