AwanSolveAi

Warranty Claim Cover Sheet

General heavy-equipment synthetic claim form

Field	Value
Claim ID	DEMO-011
Equipment	Industrial Engine
Model	IE-Q6
Serial	ENG-Q6-7712
Operating Hours	6930
Claim Date	2026-09-14

Customer Complaint

Low oil pressure warning under warm idle.

Failure / Fault Code

ECM-0521

Claimed Cause

Oil pressure sender reading out of tolerance

Correction

Replaced oil pressure sender

Claimed Part

OPS-771

Claimed Labor

2.0 h

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD