AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-013
Technician	Technician M
Equipment	Industrial Engine

Complaint

Low oil pressure warning under warm idle.

Diagnosis

Performed Engine oil pressure.

Cause

Oil pressure sender reading out of tolerance

Correction

Replaced oil pressure sender. Installed part OPS-771.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD