AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-014
Technician	Technician N
Equipment	Industrial Engine

Complaint

Low oil pressure warning under warm idle.

Diagnosis

Performed Engine oil pressure.

Cause

Possible sender issue; cause not confirmed.

Correction

Replaced oil pressure sender. Installed part OPS-771.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD