AwanSolveAi

Warranty Claim Cover Sheet

General heavy-equipment synthetic claim form

Field	Value
Claim ID	DEMO-020
Equipment	Compressor
Model	AC90
Serial	CMP-90-4147
Operating Hours	5512
Claim Date	2026-09-03

Customer Complaint

Low discharge pressure and extended recovery time.

Failure / Fault Code

P-LOW

Claimed Cause

Discharge valve leakage

Correction

Replaced discharge valve assembly

Claimed Part

DV-903

Claimed Labor

4.0 h

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD