Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-001
Technician	Validation Technician

Reported Complaint

Compressor cycles excessively at steady demand.

Test Performed

Receiver pressure decay

Confirmed Cause

Check valve leakage

Repair Action

Replaced receiver check valve

Installed Part

CV-110

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD