Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-002
Machine Model	T190
Machine Serial	AG-190-7002
Machine Hours	1574
Repair Opened	2026-08-03
Repair Completed	2026-08-04

Reported Symptom

Hydraulic remotes lose pressure under load.

Repair Performed

Replaced remote valve cartridge

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD