Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-003
Machine Model	E67
Machine Serial	EN-67-7003
Machine Hours	1611
Repair Opened	2026-08-04
Repair Completed	2026-08-05

Reported Symptom

Engine hunts at low idle after warm-up.

Repair Performed

Replaced fuel metering actuator

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD