Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-006
Machine Model	F45E
Machine Serial	FL-45-7006
Machine Hours	1722
Repair Opened	2026-08-07
Repair Completed	2026-08-08

Reported Symptom

Truck loses drive intermittently after 20 minutes.

Repair Performed

Repaired and torqued power terminal

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD