Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-007
Equipment Type	Compressor
Asset Model	C110
Asset Serial Number	CP-110-7007
Meter Hours	1759
Customer Concern	Compressor cycles excessively at steady demand.
Diagnostic Code	PRS-11
Root Cause	Possible issue; cause not confirmed.
Corrective Action	Replaced receiver check valve
Replacement Part	CV-110
Labor Claimed	3.0 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD