Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-009
Machine Model	E67
Machine Serial	EN-67-7009
Machine Hours	1833
Repair Opened	2026-08-10
Repair Completed	2026-08-11

Reported Symptom

Engine hunts at low idle after warm-up.

Repair Performed

Replaced fuel metering actuator

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD