Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-014
Machine Model	T190
Machine Serial	AG-190-7014
Machine Hours	2018
Repair Opened	2026-08-15
Repair Completed	2026-08-16

Reported Symptom

Hydraulic remotes lose pressure under load.

Repair Performed

Replaced remote valve cartridge

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD