Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-015
Machine Model	E67
Machine Serial	EN-67-7015
Machine Hours	2055
Repair Opened	2026-08-16
Repair Completed	2026-08-17

Reported Symptom

Engine hunts at low idle after warm-up.

Repair Performed

Replaced fuel metering actuator

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD