Dealer Warranty Claim

AwanSolveAi External Validation Pack V1

Field	Value
Claim Reference	EXT-001
Equipment / Machine Type	Forklift
Equipment Model #	BG-E45
Serial #	BG45-8201
Hour Meter Reading	2261
Description of Fault	Hydraulic/output performance becomes unstable after sustained operation.
Failure Code	EXT-42
Nature of Fault	Electrical feedback connector resistance caused unstable control signal.
Corrective Procedure	Connector repaired, terminals secured, and system retested.
Blue Giant Part #	CN-4421
Labor Total Hours	3.5 hours

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD