Generator Warranty Claim

AwanSolveAi External Validation Pack V1

Field	Value
Claim Reference	EXT-005
Equipment / Machine Type	Generator
Equipment Model #	ANA-G180
Serial #	ANA18-8205
Operating Hours	2505
Damage Description	Hydraulic/output performance becomes unstable after sustained operation.
Failure Code	EXT-42
Mechanic Findings	Electrical feedback connector resistance caused unstable control signal.
Repair Description	Connector repaired, terminals secured, and system retested.
ID Number 1	CN-4421
Labor & Third-Party Cost Hours	3.5 hours
Engine Number	EN-77821
Load	75%
Voltage Phase	Three-Phase
L-N	231 V
L-L	400 V
Outside Temperature	31 C

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD