Dealer Service Record

AwanSolveAi External Validation Pack V1

Field	Value
Repair Order	RO-00006
Asset Model	ANA-G180
Machine Serial	ANA18-8206X
Meter Hours	2566
Repair Completion Date	2026-09-18

Reported Symptom

Hydraulic/output performance becomes unstable after sustained operation.

Repair Action

Connector repaired, terminals secured, and system retested.

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD