Dealer Service Record

AwanSolveAi External Validation Pack V1

Field	Value
Repair Order	RO-00007
Asset Model	HS-RT200
Machine Serial	HS200-8207
Meter Hours	2627
Repair Completion Date	2026-09-18

Reported Symptom

Hydraulic/output performance becomes unstable after sustained operation.

Repair Action

Connector repaired, terminals secured, and system retested.

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD