Dealer Service Record

AwanSolveAi External Validation Pack V1

Field	Value
Repair Order	RO-00011
Asset Model	RZ-RW55
Machine Serial	RZ55-8211
Meter Hours	2871
Repair Completion Date	2026-09-18

Reported Symptom

Hydraulic/output performance becomes unstable after sustained operation.

Repair Action

Connector repaired, terminals secured, and system retested.

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD