Dealer Service Record

AwanSolveAi External Validation Pack V1

Field	Value
Repair Order	RO-00014
Asset Model	KT-SC40
Machine Serial	KT40-8214
Meter Hours	3054
Repair Completion Date	2026-09-18

Reported Symptom

Hydraulic/output performance becomes unstable after sustained operation.

Repair Action

Connector repaired, terminals secured, and system retested.

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD