Diagnostic Test and Verification

AwanSolveAi External Set C

Field	Value
Claim ID	EXTC-001
Asset Model	PL-JRB90
Serial Number	PAL90-1201
Verification Date	2026-09-26

Diagnostic Procedure

System operating performance test

Measured Result

23.8 MPa

Post-Repair Verification

Post-repair operational test PASS

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD