Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-001
Machine Model	ZX210
Machine Serial	HX-210-7001
Machine Hours	1537
Repair Opened	2026-08-02
Repair Completed	2026-08-03

Reported Symptom

Hydraulic response becomes slow when warm.

Repair Performed

Overhauled main hydraulic pump

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD