Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-004
Machine Model	C110
Machine Serial	CP-110-7004
Machine Hours	1648
Repair Opened	2026-08-05
Repair Completed	2026-08-06

Reported Symptom

Compressor cycles excessively at steady demand.

Repair Performed

Replaced receiver check valve

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD