Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-008
Machine Model	WL650
Machine Serial	LD-650-7008
Machine Hours	1796
Repair Opened	2026-08-09
Repair Completed	2026-08-10

Reported Symptom

Lift arms settle after engine shutdown.

Repair Performed

Replaced lift control valve

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD