Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-014
Machine Model	WL650
Machine Serial	LD-650-7014
Machine Hours	2018
Repair Opened	2026-08-15
Repair Completed	2026-08-16

Reported Symptom

Lift arms settle after engine shutdown.

Repair Performed

Replaced lift control valve

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD