# Service Work Order

AwanSolveAi validation corpus

| Field | Value |
|---|---|
| Claim No. | A-017 |
| Machine Model | T190 |
| Machine Serial | AG-190-7017 |
| Machine Hours | 2129 |
| Repair Opened | 2026-08-18 |
| Repair Completed | 2026-08-19 |

## Reported Symptom

Hydraulic remotes lose pressure under load.

## Repair Performed

Replaced remote valve cartridge

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD