# Service Work Order

AwanSolveAi validation corpus

| Field | Value |
|---|---|
| Claim No. | A-019 |
| Machine Model | ZX210 |
| Machine Serial | HX-210-7019 |
| Machine Hours | 2203 |
| Repair Opened | 2026-08-20 |
| Repair Completed | 2026-08-21 |

## Reported Symptom

Hydraulic response becomes slow when warm.

## Repair Performed

Overhauled main hydraulic pump

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD