Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-025
Machine Model	ZX210
Machine Serial	HX-210-7025
Machine Hours	2425
Repair Opened	2026-08-06
Repair Completed	2026-08-07

Reported Symptom

Hydraulic response becomes slow when warm.

Repair Performed

Overhauled main hydraulic pump

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD