Service Work Order

AwanSolveAi validation corpus

Field	Value
Claim No.	A-020
Machine Model	WL650
Machine Serial	LD-650-7020
Machine Hours	2240
Repair Opened	2026-08-01
Repair Completed	2026-08-02

Reported Symptom

Lift arms settle after engine shutdown.

Repair Performed

Replaced lift control valve

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD