





# Permeation Chamber Design



- Poor Sealing
- Poor Compression
- No O-Rings






- 3-Piece Design
- Quad-Ring Seals
- Tissue compression



- Air Relief

- Electrode Port



Tom