

ALATAS CAR RENTAL SERVICES

PHIDCO LOT, BALIWASAN, ZAMBOANGA CITY

Contact No.: 09263943351



VEHICLE RETURN DAMAGE INSPECTION & ACKNOWLEDGMENT

Date: **2026-09-22**

Related Rental Agreement Date/No.: **r-1790075843095**

RENTER / LESSEE INFORMATION

Full Name: **EXAMPLE EXAMPLE EXAMPLE**

Address: **RECODO ROAD, RECODO, ZAMBOANGA CITY, ZAMBOANGA DEL SUR**

Contact No.: **+63 922 222 2222**

VEHICLE INFORMATION

Make/Model: **EXAMPLE EXAMPLE**

Plate No.: **1122331122**

Engine No.: **ASDASD2132132**

Chassis No.: **ASDAS2132132**

RETURN DETAILS

Date Returned: **2026-09-22**

Time Returned: **PM** AM / PM

Odometer Reading: **170000**

Fuel Level: **2**

DAMAGE / CONDITION FOUND UPON RETURN

Upon return of the above-described vehicle to ALATAS CAR RENTAL SERVICES, the vehicle was physically inspected and the following damage, loss, or abnormal condition was observed:

Location/Part: **IPIL**

Description of Damage: **VECHICULAR CRASH**

Additional Damage / Missing Item / Other Issue: **NO HEADLIGHT NO BUMPER**

Damage Type: ☐ Scratch ☐ Dent ☐ Cracked/Broken Part ☒ Collision Damage

☐ Tire/Wheel Damage ☐ Glass/Light Damage ☒ Interior Damage ☒ Missing Item/Accessory

☐ Mechanical/Operational Issue ☐ Other: _____

Photos/Videos Taken: ☒ YES ☐ NO Number of Photos/Videos: **2**

DAMAGE ASSESSMENT

☐ Repair cost has not yet been determined and the vehicle will be submitted for proper inspection/quotation.

☐ Estimated repair cost: P _____

☒ Final quotation/assessment attached.

If the amount stated above is only an estimate, it is not the final amount. The final amount shall be based on the actual inspection, repair quotation, replacement parts, labor, towing, and other reasonable expenses arising from the damage, subject to the Vehicle Rental Agreement.

ALATAS CAR RENTAL SERVICES
PHIDCO LOT, BALIWASAN, ZAMBOANGA CITY
Contact No.: 09263943351



RENTER'S ACKNOWLEDGMENT

I, the undersigned RENTER/LESSEE, acknowledge that I was present during, or was informed of, the return inspection and that the damage/condition described in this document was observed and documented upon return of the vehicle.

My signature below confirms receipt and acknowledgment of this inspection report and the stated condition of the vehicle. Any determination of responsibility and the amount chargeable shall be governed by the Vehicle Rental Agreement and supported, where applicable, by inspection findings, photographs/videos, quotations, receipts, or other relevant records.

PAYMENT / SETTLEMENT STATUS

- ☐ For assessment - amount to be determined
☒ Renter agrees to pay based on final repair quotation/actual cost
☐ Paid P_____ on _____
☐ Partial payment P_____ Balance P_____
☐ Other arrangement: _____

Payment or settlement under this document does not cover additional concealed or mechanical damage that could not reasonably have been discovered during the initial return inspection and is subsequently determined to be related to the rental period, subject to the Vehicle Rental Agreement and applicable law.

LESSEE / RENTER

Signature Over Printed Name

EXAMPLE EXAMPLE EXAMPLE

License No: J64545454

License Valid Until: _____

Date: **2026-09-22**

**LESSOR /
AUTHORIZED REPRESENTATIVE**

Signature Over Printed Name

Alatas Admin

WITNESS

Signature: _____ Printed Name: JUBAIRA Date/Time: **2026-09-22 3:30 PM**

ATTACHMENTS

- ☒ Vehicle return photographs ☐ Video documentation ☐ Repair quotation ☐ Parts/labor estimate
☐ Copy of Rental Agreement ☐ Other: _____

ALATAS CAR RENTAL SERVICES

PHIDCO LOT, BALIWASAN, ZAMBOANGA CITY
Contact No.: 09263943351



ATTACHED MEDIA (APPENDIX)

Vehicle return photograph 1



Vehicle return photograph 2

