CHUKWUEMEKA OSMUND AZODO

SENIOR MACHINERY ENGINEER | TURBOMACHINERY RELIABILITY & INTEGRITY | OIL & GAS

+234 703 087 2333 | azodoemeka@gmail.com | www.linkedin.com/in/azodoemeka | Eket, Akwa Ibom, Nigeria

B.Eng Mechanical Engineering | ASQ Certified Reliability Engineer (CRE) | COREN R.Engr | ASME, SPE, NSE, ASQ

22 October 2026

Hiring Team
Seplat Energy Plc
Lagos, Nigeria

Application: Senior Machinery Engineer (Requisition 762)

Dear Hiring Team,

I am applying for the Senior Machinery Engineer position (Requisition 762). I am a mechanical engineer with 12 years in turbomachinery and rotating/packaged equipment reliability, an ASQ Certified Reliability Engineer and a member of several engineering bodies. I am currently the Machinery Engineer for the Oso Gas Hub, the key enabler of Seplat's 120 → 240 MMSCFD sales gas ambition, and this role is a natural extension of the discipline ownership I already exercise across these assets.

Equipment-health surveillance and troubleshooting are the substance of my current role. I review vibration spectra and trends, lube-oil analysis, compressor performance maps, turbine parameters and pump curves across HP and LP centrifugal compressors, turbo-expanders, gas turbines, and cryogenic and API 610 pumps, through SolarInsight, Seeq and PI XHQ, converting degradation signals into owned interventions with operations, maintenance and asset management.

When a bundle change-out left a 130 MMSCFD compressor with severe vibration, I led the RCA with the OEM and in-house teams, mapped the contamination paths and ran sectioned borescope inspection of the cooler bundles; the cause proved to be debris-induced rotor unbalance, and piping cleaning, lube-oil flushing and re-inspection returned the machine to service within ISO vibration limits. A separate fleet-wide RCFA (fifteen years of records, using pooled failure-rate and Crow-AMSAA reliability-growth analysis) let me show the affected compressors failing roughly 17× more often than a comparable benchmark unit on the same platform, and trace the cause to a wrong-specification filter element fitted into a housing built for now-discontinued OEM hardware. I engaged the OEM and an alternative supplier on a validated fix, packaged into an eleven-action closeout with named owners and dates.

Lifecycle and obsolescence risk, and vendor/workshop assurance, are also familiar ground: an RCFA and API 610 review of a chronically failing depropaniser pump at BRT found it running outside its design envelope on hydraulic selection and mechanical seal configuration, and I have led RCA and structural reinforcement for foundation cracking across multiple pumps and generators. I strengthened Oso's Pre-Startup Safety Review process to capture off-skid activities it had missed, now tailored to each bundle change-out, and maintain an appreciable record of identifying and following up on hazards under Seplat's Hazard Identification & Control Scheme.

I bring six years managing machinery efficiency, reliability improvement and technology innovation for a multi-site gas turbine generating company, where I led Reliability-Centred Maintenance deployment, managed OEM Factory Acceptance Tests, and designed and deployed IIoT-based condition monitoring that delivered around ten per cent in operating cost savings. I also coach engineers and maintenance personnel and share lessons learned to standardise good practice across assets, and I was recognised with FIPL's Safety Sentinel and Safety Advocate of the Year awards for consistent hazard identification and follow-up.

Thank you for considering my application. I would welcome the opportunity to bring this track record of ownership, troubleshooting and reliability improvement to the Senior Machinery Engineer role.

Yours sincerely,

Chukwuemeka Osmund Azodo