## PHILIPPINE BATTERIES, INC. Plates Department

## **GREEN PLATE MONITORING SHEET**

Production Date: 26-Sep-23 Sheet No.: P12-23D-0922

Curing Booth: OSI 2

		1	1	1		
SN	Line	Shift	Rack No.	Plate Type	Oxide Type	Result
1	Delphi 1	2nd-D	76	PUEPTA087MP-E	Eagle 1	
2	Delphi 3	2nd-D	0921	XUEZTA087MP	Penarroya 2	
3	Delphi 2	2nd-D	PL-134	PUEPTA087MP-E	Penarroya 1	
4	Delphi 3	2nd-D	0697	XUEZTA087MP	Penarroya 2	
5	Delphi 2	2nd-D	714	PUEPTA087MP-E	Penarroya 1	
6	Delphi 3	2nd-D	110	XUEZTA087MP	Penarroya 2	
7	Delphi 2	2nd-D	A-0172	PUEPTA087MP-E	Penarroya 1	
8	Delphi 1	2nd-D	45	PUEPTA087MP-E	Eagle 1	
9	Delphi 3	2nd-D	16	XUEZTA087MP	Penarroya 2	
10	Delphi 1	2nd-D	351	PUEPTA087MP-E	Eagle 1	
11	Delphi 2	2nd-D	28	PUEPTA087MP-E	Penarroya 1	
12	Delphi 3	2nd-D	93	XUEZTA087MP	Penarroya 2	
13	Delphi 1	2nd-D	P019	PUEPTA087MP-E	Eagle 1	
14	Delphi 2	2nd-D	20	PUEPTA087MP-E	Penarroya 1	
15	Delphi 3	2nd-D	56	XUFZTA087MP	Penarrova 2	