## PHILIPPINE BATTERIES, INC. Plates Department

## **GREEN PLATE MONITORING SHEET**

Production Date: 22-Dec-23 Sheet No.: P12-23D-1317

Curing Booth: OSI 9

SN	Line	Shift	Rack No.	Plate Type	Oxide Type	Result
1	Delphi 1	2nd-D	17	PUEPTA087MP-E	Eagle 2	
2	Delphi 3	2nd-D	99	XU72ZSOMP	Penarroya 1	
3	Delphi 1	2nd-D	53	XUEZTA087MP	Eagle 2	
4	Delphi 3	2nd-D	71	XU72ZSOMP	Penarroya 1	
5	Delphi 1	2nd-D	508	PUEPTA087MP-E	Eagle 2	
6	Delphi 3	2nd-D	92	XU72ZSOMP	Penarroya 1	
7	Delphi 2	2nd-D	A-27	PUEPTA087MP-E	Eagle 2	
8	Delphi 2	2nd-D	97	PUEPTA087MP-E	Eagle 2	
9	Delphi 3	2nd-D	2	XU72ZSOMP	Penarroya 1	
10	Delphi 1	2nd-D	'05	PUEPTA087MP-E	Eagle 2	
11	Delphi 1	2nd-D	N-135	PUEPTA087MP-E	Eagle 2	
12	Delphi 3	2nd-D	PL142	XU72ZSOMP	Penarroya 1	
13	Delphi 2	2nd-D	82	PUEPTA087MP-E	Eagle 2	
14	Delphi 1	2nd-D	104	PUEPTA087MP-E	Eagle 2	
15	Delphi 2	2nd-D	43	PUEPTA087MP-E	Eagle 2	
16	Delphi 1	2nd-D	23	PUEPTA087MP-E	Eagle 2	