

PHILIPPINE BATTERIES, INC.
Plates Department
GREEN PLATE MONITORING SHEET

Production Date: **19-Aug-23**

Sheet No.: **P12-23D-0799**

Curing Booth: **OSI 11**

| SN | Line | Shift | Rack No. | Plate Type | Oxide Type | Result |
|-----------|-------------|--------------|-----------------|-------------------|-------------------|---------------|
| 1 | Cominco 2 | 3rd | PL-112 | PUEPTA087MP-E | Penarroya 1 | |
| 2 | Cominco 2 | 3rd | 4 | PUEPTA087MP-E | Penarroya 1 | |
| 3 | Cominco 2 | 3rd | 0127 | PUEPTA087MP-E | Penarroya 1 | |
| 4 | Cominco 2 | 3rd | N-116 | PUEPTA087MP-E | Penarroya 1 | |
| 5 | Cominco 2 | 1st | PL051 | PUEPTA087MP-E | Penarroya 1 | |
| 6 | Cominco 2 | 1st | 32 | PUEPTA087MP-E | Penarroya 1 | |
| 7 | Cominco 2 | 1st | 21 | PUEPTA087MP-E | Penarroya 1 | |
| 8 | Cominco 2 | 1st | PL109 | PUEPTA087MP-E | Penarroya 1 | |