

GREEN PLATE MONITORING SHEETProduction Date: **25-Sep-23**Sheet No.: **P12-23D-0917**Curing Booth: **OSI 12**

SN	Line	Shift	Rack No.	Plate Type	Oxide Type	Result
1	Delphi 2	2nd-N	N117	PUEPTA087MP-E	Eagle 1	
2	Delphi 2	2nd-N	11	PUEPTA087MP-E	Eagle 1	
3	Delphi 1	2nd-N	111	PUEPTA087MP-E	Eagle 1	
4	Delphi 3	2nd-N	6	XU60ZSOMP	Penarroya 2	
5	Delphi 2	2nd-N	13	PUEPTA087MP-E	Eagle 1	
6	Delphi 3	3rd	100	XU60ZSOMP	Penarroya 2	
7	Delphi 2	3rd	PL-097	PUEPTA087MP-E	Eagle 1	
8	Delphi 1	3rd	114	PUEPTA087MP-E	Eagle 1	
9	Delphi 1	3rd	31	PUEPTA087MP-E	Eagle 1	
10	Delphi 3	3rd	07	XU60ZSOMP	Penarroya 2	
11	Delphi 2	3rd	PL-071	PUEPTA087MP-E	Eagle 1	
12	Delphi 3	3rd	019	XU60ZSOMP	Penarroya 2	
13	Delphi 1	3rd	M2	PUEPTA087MP-E	Eagle 1	
14	Delphi 3	3rd	PL-154	XU60ZSOMP	Penarroya 2	
15	Delphi 2	3rd	A21	PUEPTA087MP-E	Eagle 1	
16	Delphi 2	3rd	PL-066	PUEPTA087MP-E	Eagle 1	