

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY
AIR QUALITY DIVISION

Activity Report: On-Site Inspection

FACILITY: WEXFORD COUNTY LANDFILL (N3862)		SRN / ID: N3862
LOCATION: 990 N MACKINAW TRL		DISTRICT: Cadillac
CITY: MANTON		COUNTY: Wexford
CONTACT:		ACTIVITY DATE: September 19, 2011
STAFF: Robert Dickman (INACTIVE)	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Scheduled inspection of this ROP source.		
RESOLVE COMPLAINTS:		

Inspected this source as per ROP Number MI-ROP-N3862-2007. This ROP expires in July of 2012. Prior to entering the facility, it was noted that winds were light and out of the southwest with rain. No odors were noted downwind of the facility.

This facility is subject to 40 CFR 60 Subpart WWW. Much of this subpart will not apply to a facility unless non-methane organic compound (NMOC) emissions are greater than 50 megagrams per year (Mg/yr). Compliance with this is determined through testing called Tier 2 testing. The last Tier 2 testing performed at this facility was in March of 2011, and indicated NMOC emissions of 7.85 Mg/yr. Consequently, much of Subpart WWW and the ROP conditions associated with it will not apply. Following are the findings of the inspection based on currently applicable conditions:

EULANDFILL<50

As stated above, the only conditions that are applicable in this emission unit are those associated with the Tier 2 testing. This testing performed in March of 2011 and appears to be correct. All reporting associated with this testing has been completed and the facility has submitted annual NMOC emissions estimates (via MAERS) as required. All other conditions are not applicable until the 50 Mg/yr NMOC emissions threshold has been exceeded.

EUASBESTOS

I. There are no emission limits associated with this EU.

II. There are no material limits associated with this EU.

III.1.a-d - There are no visible emissions from this EU because of the way asbestos containing waste is handled: The generator must notify the facility in advance that the waste is coming to the facility. The location where the waste is to be placed is surveyed in and mapped for not only north and west coordinates but also elevation. Waste is placed in the cell and immediately buried. Eliminating the possibility of opacity from and human contact with the material.

IV.1.a - Placement of all asbestos containing materials in the landfill is mapped and will be excluded from placement of gas collection systems. Currently there is no gas collection system at the facility.

V. There is no testing required for this EU.

NAME _____ DATE _____ SUPERVISOR _____

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY
AIR QUALITY DIVISION

Activity Report: On-Site Inspection

VI.1.a-c - Records regarding placement of asbestos containing waste are being kept and were available upon request.

VI.2 - The location where the waste is to be placed is surveyed in and mapped for not only north and west coordinates but also elevation.

VI.3 - Records regarding placement of asbestos containing waste are being kept and were available upon request.

VII.1-3 - All semi-annual and annual reporting for this EU has been performed in a timely manner.

VII.4 - This landfill has not closed, therefore this condition does not apply.

VII.5 - All records associated with this EU were available.

VII.6.a-d - There were no records of asbestos containing waste being disturbed or relocated.

VIII - There are no stack restrictions associated with this EU.

IX - There are no other requirements associated with this EU.

At the time of the inspection, this facility was in compliance with their ROP.

NAME _____ DATE _____ SUPERVISOR _____