

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY
AIR QUALITY DIVISION

Activity Report: Test Observation

FACILITY: WEXFORD COUNTY LANDFILL (N3862)	SRN / ID: N3862
LOCATION: 990 N MACKINAW TRL	DISTRICT: Cadillac
CITY: MANTON	COUNTY: Wexford
CONTACT:	ACTIVITY DATE: March 08, 2022
STAFF: Robert Dickman (INACTIVE)	COMPLIANCE STATUS: Compliance
SOURCE CLASS:	
SUBJECT: Site visit regarding Tier 2 testing at this facility.	
RESOLVE COMPLAINTS:	

Visited this facility to check on Tier 2 testing being performed at this facility. This testing is being performed per 40 CFR 62 Subpart OOO and 40 CFR 63 Subpart AAAA. The facility is testing to attempt to demonstrate Non Methane Organic Compound emissions of less than 34 Megagrams per year. Emissions above this threshold require the facility install and maintain a Landfill Gas Collection and Control System (GCCS). The landfill currently has voluntarily installed a GCCS but is not required to monitor and operate it in accordance with the federal standards.

I met with Terry Whetstone, Operations Manager at the facility. There is not much observable activity associated with Tier 2 testing at the facility as it is mostly composite gas sampling from different areas of the landfill through the installed GCCS. Mr. Whetstone indicated that this sampling was going well with at least 60% gas at most locations sampled. We then toured the landfill and met with the testing contractor performing the sampling (EIL). He reiterated Mr. Whetstone's assertion that sampling was going well. At that time, we were near a part of the landfill on the north side that was suspected of being a cause of odors as the GCCS for that area was watered in and no gas was being collected. A noticeable odor was noted from this area. Mr. Whetstone indicated repairing this area was going to be included in work on the GCCS to take place beginning as soon as the ground has thawed enough to move heavy equipment to the site.

NAME _____ DATE _____ SUPERVISOR _____