

DECTCAR VEHICLE INSPECTION REPORT

Vehicle Information

Brand	Toyota
Model	Corolla
Plate	123456-A-5
Year	2022
Inspection Date	2026-08-07

Detected Defects

Defect	Confidence	Severity
--------	------------	----------

Inspection Summary

****Vehicle Inspection Report****

****Vehicle Information:****

- * Brand: Toyota
- * Model: Corolla
- * Plate: 123456-A-5
- * Year: 2022

****Inspection Summary:****

This vehicle inspection was conducted on August 7, 2026, to assess the overall condition of the vehicle. The inspection was performed by a certified automotive inspection expert.

****Overall Vehicle Condition:****

The vehicle was found to be in excellent condition, with no detected defects. The exterior and interior of the vehicle were clean and well-maintained. The tires were properly inflated, and the brakes were functioning smoothly.

****Maintenance Recommendations:****

Based on the inspection, the following maintenance recommendations are suggested:

- * Regular oil changes every 5,000 to 7,500 miles to maintain engine performance and longevity.
- * Tire rotation every 5,000 to 8,000 miles to ensure even tread wear and extend tire life.
- * Brake pad inspection every 10,000 to 15,000 miles to prevent brake wear and ensure safe braking performance.
- * Regular vehicle cleaning and waxing to maintain the exterior paint and protect the vehicle from the

elements.

****Inspection Date:**** August 7, 2026

****Inspection Number:**** [Insert inspection number]

****Certification:**** This inspection report is certified by a certified automotive inspection expert.

Note: This report is for informational purposes only and may not be used for insurance or warranty purposes.

Overall Condition

Excellent

Maintenance Recommendation

No maintenance is required. The vehicle is in excellent condition.

*Generated automatically by DectCar AI
07/08/2026 14:15*