

Reject Report from 8/6/2026 thru 8/20/2026

Reject Summary	PGE Oil Pan DC - 111	P8A Cam Thrust Cover Front DC - 114	P8A Case Oil Seal DC - 116	P8A Oil Pan DC - 118	RPY Holder Comp No 1 In Cam - 120	RPY Holder Comp No 2 In Cam - 121	RPY Holder Comp No 3 In Cam - 122	RPY Holder Comp No 4 In Cam - 123
Total Rejects	0	0	0	0	2	1	0	0
Die Cast Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	1	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	0	0	9,484	9,483	9,484	9,484
Reject	0	0	0	0	2	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.02%	0.00%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	0	0
Test Parts	0	0	0	0	0	0	0	0
Reject Description								
DC - Broken Gate						1		
MS - Holesize					2			

Reject Summary	RPY Holder Comp No 5 in Cam - 124	RPY Holder Comp No 1 Ex Cam - 125	RPY Holder Comp No 2 Ex Cam - 126	RPY Holder Comp No 3 Ex Cam - 127	RPY Holder Comp No 4 Ex Cam - 128	RPY Holder Comp No 5 Ex Cam - 129	RPY Holder Comp No 6 Ex Cam - 130	RPY Holder Comp No 1 Exh Cam Lwr - 131
Total Rejects	113	125	1	0	0	151	169	30
Die Cast Production	9,912	11,652	11,652	11,652	11,652	9,912	9,912	4,578
Reject	100	0	1	0	0	96	114	30
Reject %	1.01%	0.00%	0.01%	0.00%	0.00%	0.97%	1.15%	0.66%
Trim Shop Production	0	4,802	3,195	7,297	0	0	376	5,435
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	9,476	9,342	9,466	9,716	9,466	9,470	9,469	9,728
Reject	13	125	0	0	0	55	55	0
Reject %	0.14%	1.32%	0.00%	0.00%	0.00%	0.58%	0.58%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	0	0
Test Parts	43	89	89	96	90	50	51	39
Reject Description								
DC - Blisters	3							
DC - Broken Gate	1							
DC - Computer reject/Biscuit Size	96					96	96	24
DC - Computer reject/Rise up time								6
DC - Flash							15	
DC - Hit Damage/Dent/Scratch/Nick							3	
DC - Soldering			1					
DC - Test Part	43	89	89	96	90	50	51	39
MS - Assembled on to NG part MS	79					82	82	
MS - Cycle Stop						55	55	
MS - Dimensional (All dimensional except pin size and or depth/height)		125						
MS - Unidentified Part	13							

Reject Summary	RPY Holder Comp No 2 Exh Cam Lwr - 132	RPY Holder Comp No 3 Exh Cam Lwr - 133	RPY Holder Comp No 4 Exh Cam Lwr - 134	RPY Holder Comp No 1 Rkr Shaft - 135	RPY Holder Comp No 2 Rkr Shaft - 136	RPY Holder Comp No 3 Rkr Shaft - 137	RPY Holder Comp No 4 Rkr Shaft - 138	RPY Holder Comp No 5 Rkr Shaft - 139
Total Rejects	30	30	44	22	18	18	18	5
Die Cast Production	4,578	4,578	4,578	2,156	14,064	14,064	14,064	0
Reject	30	30	44	0	0	0	0	0
Reject %	0.66%	0.66%	0.96%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	6,033	7,073	9,529	7,981	9,506	9,892	13,640	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	9,728	9,728	9,407	9,020	9,022	9,027	9,027	0
Reject	0	0	0	22	18	18	18	5
Reject %	0.00%	0.00%	0.00%	0.24%	0.20%	0.20%	0.20%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	1	1	1	1	0
Test Parts	39	39	39	16	64	64	64	0
Reject Description								
DC - Broken Gate			13					
DC - Computer reject/Biscuit Size	24	24	24					
DC - Computer reject/Rise up time	6	6	6					
DC - Missing Material			1					
DC - Test Part	39	39	39	16	64	64	64	
MS - Cycle Stop								5
MS - Holesize				2				
MS - Machine Trial				1	1	1	1	
MS - Tool Break				7	7	7	7	
MS - Tool Mark				11	11	11	11	
MS - Unidentified Part				2				

Reject Summary	5BAA Holder Comp #5 R/S - 140	5BA CH/RS SET - 141	RPY CH/RS SET - 142	5PA Fuel Pump - 143	B Adaptor DC - 150	C Adaptor DC - 151	59B Base Comp Fuel Pump - 152	RPY Fuel Pump - 153
Total Rejects	666	5	0	2	0	0	0	0
Die Cast Production	7,579	0	0	0	0	0	0	0
Reject	297	0	0	0	0	0	0	0
Reject %	3.92%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	8,052	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	8,653	8,208	0	576	0	0	0	0
Reject	369	5	0	2	0	0	0	0
Reject %	4.09%	0.06%	0.00%	0.35%	0.00%	0.00%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	29	13	0	0	0	0	0	0
Test Parts	83	0	0	0	0	0	0	0
Reject Description								
DC - Broken Gate	5							
DC - Computer reject/Biscuit Size	24							
DC - Contamination	2							
DC - Failed Leak Test	50							
DC - Flow Lines	17							
DC - Hard Spot	1							
DC - Hit Damage/Dent/Scratch/Nick	20							
DC - NCU - Non Clean Up	1							
DC - Over File	4							
DC - Over Grind	2							
DC - Porosity	8							
DC - Porosity in Gate Area	11							
DC - Soldering	152							
DC - Test Part	83							
MS - Assembled on to NG part MS	3							
MS - Cycle Stop	51							
MS - Dimensional (All dimensional except pin size and or depth/height)	107	5						
MS - Dropped	14							
MS - Hit Damage/Dent/Scratch/Nick	70							
MS - Holesize	2			2				
MS - Machine Trial	29	13						
MS - NCU - Non Clean Up	2							
MS - Skipped Proccess	6							
MS - Steel Ball No Good	113							
MS - Tool Mark	4							

Reject Summary	5BA Side Cover - 154	5J6-1 OIL PAN DC - 155	5J6- A000 Oil Pan - 156	5K8 Oil Pan - 157	59B Thermo Cover - 158	V6 Adaptor DC - 160	288 Throttle Body DC - 161	320 Throttle Body DC - 162
Total Rejects	0	476	0	0	0	0	0	0
Die Cast Production	0	5,240	0	0	0	0	0	0
Reject	0	442	0	0	0	0	0	0
Reject %	0.00%	8.44%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	5,826	0	0	0	0	0	0
Reject	0	34	0	0	0	0	0	0
Reject %	0.00%	0.58%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	1	0	0	0	0	0	0
Test Parts	0	54	0	0	0	0	0	0
Reject Description								
DC - Breakout (Broken Die)		1						
DC - Broken/Bent Pin		243						
DC - Chipped Bolt Pad		12						
DC - Computer reject/Biscuit Size		24						
DC - Computer reject/High Speed		24						
DC - Computer reject/Rise up time		3						
DC - Failed Leak Test		37						
DC - Flatness/Bent Parts		24						
DC - Flow Lines		45						
DC - Porosity		12						
DC - Surface Void (not including caused by broken gate)		2						
DC - Test Part		54						
DC - Trim Damage		15						
MS - Cycle Stop		1						
MS - Dropped		1						
MS - Hit Damage/Dent/Scratch/Nick		16						
MS - Holesize		2						
MS - Machine Trial		1						
MS - Misset		1						
MS - Tool Mark		13						

Reject Summary	5K8 Oil Pan (Metts) - 164	R70 Case Oil Seal - 166	CAM THRUST FRONT (HAILIN) (RW) - 167	5BA SIDE COVER (METTS DC) - 168	59B FUEL PUMP (METTS DC) - 169	Front Cover DC - 180	ADAPTER, S/C - 181	59B PASSAGE, WATER (RW) - 182
Total Rejects	0	985	21	0	0	0	0	0
Die Cast Production	0	0	0	0	0	0	0	0
Reject	0	5	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	7,404	3,545	0	0	0	0	0
Reject	0	980	0	0	0	0	0	0
Reject %	0.00%	11.69%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	0	0
Test Parts	0	0	0	0	0	0	0	0
Reject Description								
DC - Failed Leak Test		3						
DC - Hit Damage/Dent/Scratch/Nick		1						
DC - Porosity		1						
HL - Failed Leak Test			19					
HL - Hit Damage/Dent/Scratch/Nick			2					
MS - Damaged Supply Part		974						
MS - Hit Damage/Dent/Scratch/Nick		5						
MS - Pin Damage		1						

Reject Summary	RPY BRKT, COMPRESSOR - 183	59B CASE COMP, THERMO - 184	59B Cam Holder Set (Metts) - 185	59B CAM HOLDER SET MPP (AEP) - 186	59B In Cam No 1 MPP - 187	59B In Cam No 2 MPP - 188	59B In Cam No 3 MPP - 189	59B In Cam No 4 MPP - 190
Total Rejects	0	0	0	0	1,287	82	63	53
Die Cast Production	0	0	0	0	10,920	18,098	18,098	18,098
Reject	0	0	0	0	1,277	61	49	50
Reject %	0.00%	0.00%	0.00%	0.00%	11.69%	0.34%	0.27%	0.28%
Trim Shop Production	0	0	0	0	6,064	14,871	15,340	15,382
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	0	11,990	12,435	12,838	12,838	12,838
Reject	0	0	0	0	10	21	14	3
Reject %	0.00%	0.00%	0.00%	0.00%	0.08%	0.16%	0.11%	0.02%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	0	0
Test Parts	0	0	0	0	34	54	54	54
Reject Description								
DC - Discoloration						1		
DC - Failed Leak Test						2	1	
DC - Flow Lines					1272			
DC - Porosity					2	5		1
DC - Robot Dropping Parts						46	46	46
DC - Surface Void (not including caused by broken gate)					3	7	1	3
DC - Test Part					34	54	54	54
DC - Trim Damage							1	
MS - Cycle Stop					3		1	
MS - High Pin Pressure					5	19	11	1
MS - Low Pin Pressure					2		2	2
MS - Unidentified Part						2		

Reject Summary	59B In Cam No 5 MPP - 191	59B In Cam Ex 1 MPP - 192	59B In Cam Ex 2 MPP - 193	59B In Cam Ex 3 MPP - 194	59B In Cam Ex 4 MPP - 195	59B In Cam Ex 5 MPP - 196	5PA FUEL PUMP METTS DC - 197	RKEU Casing DC - 209
Total Rejects	12	1,295	54	52	54	8	0	0
Die Cast Production	10,920	10,920	18,098	18,098	18,098	10,920	0	0
Reject	8	1,292	52	47	50	4	0	0
Reject %	0.07%	11.83%	0.29%	0.26%	0.28%	0.04%	0.00%	0.00%
Trim Shop Production	7,302	4,013	17,293	15,128	18,053	7,245	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	12,835	12,835	12,838	12,838	12,838	12,835	0	0
Reject	4	3	2	5	4	4	0	0
Reject %	0.03%	0.02%	0.02%	0.04%	0.03%	0.03%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	2	0	0	0	0
Test Parts	34	34	54	54	54	34	0	0
Reject Description								
DC - Broken Gate	1							
DC - Discoloration	1							
DC - Flow Lines		1292						
DC - Porosity	1		6		2	3		
DC - Robot Dropping Parts			46	46	46			
DC - Surface Void (not including caused by broken gate)	5			1	2	1		
DC - Test Part	34	34	54	54	54	34		
MS - Cycle Stop	2	1				3		
MS - High Pin Pressure	2	1		5	4			
MS - Low Pin Pressure		1	2			1		
MS - Machine Trial				2				

[illegible]

Reject Summary	PLE Oil Pan JP - 447	5MH Oil Pan DC - 450	P/S Front Brkt LMC - 462	RNA Oil Pan - 470	CIVIC RNA WATER PUMP - 472	RNA Lost Motion Holder - 473	RNA#1 Rocker Shaft - 474	RNA#2 Rocker Shaft - 475
Total Rejects	0	0	0	7	0	0	0	0
Die Cast Production	0	0	0	139	0	0	0	0
Reject	0	0	0	6	0	0	0	0
Reject %	0.00%	0.00%	0.00%	4.32%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	0	46	0	0	0	0
Reject	0	0	0	1	0	0	0	0
Reject %	0.00%	0.00%	0.00%	2.13%	0.00%	0.00%	0.00%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	1	0	0	0	0
Test Parts	0	0	0	0	0	0	0	0
Reject Description								
DC - Broken Gate				4				
DC - Failed Leak Test				2				
MS - Cycle Stop				1				
MS - Machine Trial				1				

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Reject Summary	R1Z CNG THERMO CASE ASSY (AEP) - 571	RNO (RNOX) OIL PAN DC - 573	SZAX BASE SUPPORT HALF SHAFT - 574	5A0A THERMO CASE (MS) - 577	5GO R/S #1 DC - 578	5GO R/S #2 DC - 579	5GO R/S #3 DC - 580	5GO HOLDER ASSY R/S FR (AEP) - 581
Total Rejects	0	0	0	0	302	147	80	0
Die Cast Production	0	0	0	0	10,161	20,322	10,161	0
Reject	0	0	0	0	292	125	68	0
Reject %	0.00%	0.00%	0.00%	0.00%	2.87%	0.62%	0.67%	0.00%
Trim Shop Production	0	0	0	0	11,726	20,482	8,475	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	0	0	12,208	21,564	11,368	2,880
Reject	0	0	0	0	10	22	12	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.08%	0.10%	0.11%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	6	75	5	0
Test Parts	0	0	0	0	45	96	43	0
Reject Description								
DC - Computer reject/Low Speed					8		8	
DC - Computer reject/Press up time						16		
DC - Contamination					16			
DC - Discoloration					171			
DC - Flow Lines					31			
DC - Hit Damage/Dent/Scratch/Nick					12	61	57	
DC - Porosity					54	48	3	
DC - Test Part					45	96	43	
MS - Cycle Stop					2		2	
MS - Dimensional (All dimensional except pin size and or depth/height)						1		
MS - Dropped					1	2	1	
MS - Flash								
MS - Hit Damage/Dent/Scratch/Nick					6	2	6	
MS - Low Pin Pressure						2	3	
MS - Machine Trial					6	75	5	
MS - NG Condition (MS)						6		
MS - Out of Sequence					1	8		
MS - Unidentified Part						1		

[illegible]

[illegible]

Reject Summary	RVS PISTON BRAKE - 598	5PA Oil Pan - 624	Pipe B Asy Diff Lube (METTS) - 625	5BF Thermo Case (METTS) - 626	PIPE B ASY DIFF LUBE (MFA) - 627	PISTON CLUTCH - 628	6B2 HOLDER COMP NO5 R/S (DC) - 629	6B2 BASE COMP FUEL PUMP (DC) - 631
Total Rejects	1	3	0	0	0	0	56	0
Die Cast Production	0	0	0	0	0	0	0	0
Reject	0	3	0	0	0	0	28	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Trim Shop Production	0	0	0	0	0	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	46	0	0	0	0	210	0
Reject	0	0	0	0	0	0	28	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	11.76%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	1	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	7	0
Test Parts	0	0	0	0	0	0	2	0
Reject Description								
DC - Failed Leak Test		3					15	
DC - Lamination							13	
DC - Test Part							2	
LMC - Hit Damage/Dent/Scratch/Nick	1							
MS - Cycle Stop							28	
MS - Machine Trial							7	

Reject Summary	6B2 Thermo Case Manual - 632	6B2 Thermo Case Auto - 633	6A0 MANUAL THERMO CASE - 634	6A0 AUTO THERMO CASE - 635	6A0 WATER PASSAGE - 636	6NA FUEL PUMP - 637	6VJ Fuel Pump - 638	5YK Pipe B Diff Lube - 640
Total Rejects	0	0	0	1	2	537	754	0
Die Cast Production	0	0	0	0	0	2,648	20,849	0
Reject	0	0	0	0	0	444	667	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	16.77%	3.20%	0.00%
Trim Shop Production	0	0	0	0	0	2,986	15,932	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	0	720	780	3,466	28,949	0
Reject	0	0	0	0	0	93	87	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	2.61%	0.30%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	1	2	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	39	46	0
Test Parts	0	0	0	0	0	17	157	0
Reject Description								
DC - Blisters							1	
DC - Breakout (Broken Die)						25		
DC - Broken Gate						184	185	
DC - Computer reject/Biscuit Size						25	5	
DC - Computer reject/Cast Pressure						6	2	
DC - Computer reject/Cycle time						18	6	
DC - Computer reject/High Speed							36	
DC - Computer reject/Rise up time						3		
DC - Contamination							3	
DC - Dents						52	4	
DC - Dimensional (All dimensional except pin size and or depth/height)						23		
DC - Failed Leak Test						19	128	
DC - Flatness/Bent Parts						2		
DC - Hit Damage/Dent/Scratch/Nick						18	49	
DC - NCU - Non Clean Up						1	8	
DC - Over File							1	
DC - Porosity						2	4	
DC - Porosity in Gate Area						16	129	
DC - Robot Dropping Parts							46	
DC - Skipped Process							3	
DC - Soldering							31	
DC - Test Part						17	157	
DC - Trim Damage						50	26	
LMC - Hit Damage/Dent/Scratch/Nick				1				
MS - Cycle Stop						18	13	
MS - Dropped							19	
MS - Hit Damage/Dent/Scratch/Nick						13	26	
MS - Holesize						9	3	
MS - Machine Trial						39	46	

MS - Missing Bolt							2	
MS - NCU - Non Clean Up							1	
MS - Oil Hole No Good						2		
MS - Pin Damage							1	
MS - Skipped Proccess						2		
MS - Thread Damage							1	
MS - Tool Break						12	2	
MS - Tool Mark						37	13	
MS - Torque No Good							6	
MT - Hit Damage/Dent/Scratch/Nick					2			

Reject Summary	6C2 Oil Pan (AEP) - 641	6L2 Oil Pan (AEP) - 642	RPY COMPRESSOR BRACKET MPP - 643	6FB Holder Comp, No 1 Cam R - 644	6FB Holder Comp, Oil Pass FRDC - 645	6FB Oil Pan - 646	64A Oil Pan - 648	69F 6MA Thermo Case/Cover Assm - 650
Total Rejects	0	0	0	1,905	36	523	542	279
Die Cast Production	0	0	0	13,770	18,904	11,298	19,209	0
Reject	0	0	0	1,811	20	436	356	121
Reject %	0.00%	0.00%	0.00%	13.15%	0.11%	3.86%	1.85%	0.00%
Trim Shop Production	0	0	0	8,532	6,487	0	0	0
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	0	0	609	11,908	9,143	9,087	13,270	16,812
Reject	0	0	0	94	12	87	186	158
Reject %	0.00%	0.00%	0.00%	0.78%	0.13%	0.95%	1.38%	0.93%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	4	0	0	0
Non-Reject Scrap								
Trial Parts	0	0	2	10	9	1	64	0
Test Parts	0	0	0	46	104	90	150	0
Reject Description								
DC - Blisters								1
DC - Breakout (Broken Die)						7		
DC - Broken Gate				107	13		22	
DC - Broken/Bent Pin						163	35	
DC - Chipped Bolt Pad						11		
DC - Computer reject/Biscuit Size				12		32	34	
DC - Computer reject/Cycle time						21		
DC - Contamination (Grease/Oil)						70		
DC - Cracks							12	
DC - Failed Leak Test						50	86	101
DC - Flaking								12
DC - Flash							3	
DC - Flatness/Bent Parts						12	3	
DC - Flow Lines				41			107	
DC - Gallings/Drags				1397				
DC - Hard Spot							4	
DC - Hit Damage/Dent/Scratch/Nick				22	3		4	7
DC - Lamination							2	
DC - NCU - Non Clean Up						1	3	
DC - No Good Date Pin						20		
DC - Over File				3				
DC - Porosity				229	4	21	30	
DC - Robot Dropping Parts						1		
DC - Short Shot						23		
DC - Surface Void (not including caused by broken gate)						1	11	
DC - Test Part				46	104	90	150	
DC - Trim Damage						3		
MS - Chatter							3	
MS - Clinch No Good							14	

MS - Cycle Stop				24	7	10	60	1
MS - Discoloration				1				
MS - Dropped				1	1	1		1
MS - Hit Damage/Dent/Scratch/Nick				3		8	10	152
MS - Holesize				30		11	38	
MS - Low Pin Pressure					2			
MS - Machine Trial			2	10	9	1	64	
MS - Misset						7		
MS - NCU - Non Clean Up				2				
MS - Out of Sequence							52	
MS - Pin Damage							2	
MS - Pin Height				2		1	1	
MS - Skipped Proccess					2		3	
MS - Stamp No Good								4
MS - Thickness				29				
MS - Tool Mark						49	3	
MS - Unidentified Part				2				
PC - Hit Damage/Dent/Scratch/Nick					2			
PC - Returned in empty dunnage								
QC - Hit Damage/Dent/Scratch/Nick					2			

Reject Summary	6MAA HOLDCOMP NO1 INTAKE (DC) - 652	6MAA HOLDCOMP NO2 INTAKE (DC) - 653	6MAA HOLDCOMP NO3 INTAKE (DC) - 654	6MAA HOLDCOMP NO4 INTAKE (DC) - 655	6MAA HOLDCOMP NO5 INTAKE (DC) - 656	6MAA HOLDCOMP NO1 EXHAUST (DC) - 657	6MAA HOLDCOMP NO2 EXHAUST (DC) - 658	6MAA HOLDCOMP NO3 EXHAUST (DC) - 659
Total Rejects	72	137	208	305	56	59	1,046	234
Die Cast Production	11,208	36,656	36,656	36,656	11,208	11,208	36,656	36,656
Reject	21	121	102	202	12	42	915	102
Reject %	0.19%	0.33%	0.28%	0.55%	0.11%	0.37%	2.50%	0.28%
Trim Shop Production	11,228	33,471	33,406	33,137	22,960	23,174	33,591	34,014
Reject	0	0	0	0	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	24,939	24,939	24,939	24,939	24,939	24,939	24,939	24,939
Reject	51	16	106	103	44	17	131	132
Reject %	0.20%	0.06%	0.42%	0.41%	0.18%	0.07%	0.52%	0.53%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	90	90	90	90	91	90	90	90
Test Parts	88	196	196	196	88	88	196	196
Reject Description								
DC - Breakout (Broken Die)							1	
DC - Broken Gate		4	3	1	1	2	3	1
DC - Contamination (Grease/Oil)				86				
DC - Flow Lines		70	70	95			70	70
DC - Hit Damage/Dent/Scratch/Nick	1							
DC - No Good Date Pin							759	
DC - Porosity	18	19	2		10	23	45	6
DC - Robot Dropping Parts		20	20	20			20	20
DC - Stuck Media	1							
DC - Surface Void (not including caused by broken gate)		8	7		1	11	16	5
DC - Test Part	88	196	196	196	88	88	196	196
DC - Trim Damage	1					6	1	
MS - Chatter								1
MS - Cycle Stop	13	4	4	4	9	2	3	2
MS - Dropped	2						3	1
MS - High Pin Pressure		2				10	81	58
MS - Hit Damage/Dent/Scratch/Nick						1		1
MS - Low Pin Pressure	5	5	48	49	12	3	10	43
MS - Machine Trial	90	90	90	90	91	90	90	90
MS - NCU - Non Clean Up						1		
MS - Oil Hole No Good	31	5	54	50	7		34	26
MS - Unidentified Part					16			

Reject Summary	6MAA HOLDCOMP NO4 EXHAUST (DC) - 660	6MAA HOLDCOMP NO5 EXHAUST (DC) - 661	6MAA HOLDCOMP SET (AEP) - 662	6MA Oil Pan (69F Finished) - 664	6MAA Thermo Cover - 667	6MAA Thermo Case - 669	6MD Intake Manifold - 674	CASE COMP INTERMEDIATE SINGLE - 679
Total Rejects	322	126	390	1,414	0	0	148	0
Die Cast Production	36,656	11,208	0	15,442	0	0	8,806	0
Reject	180	9	0	834	0	0	41	0
Reject %	0.49%	0.08%	0.00%	5.40%	0.00%	0.00%	0.47%	0.00%
Trim Shop Production	33,933	12,587	0	13,537	0	0	0	0
Reject	0	0	0	2	0	0	0	0
Reject %	0.00%	0.00%	0.00%	0.01%	0.00%	0.00%	0.00%	0.00%
Machine Shop Production	24,939	24,939	24,816	10,949	0	0	7,470	0
Reject	142	117	390	578	0	0	107	0
Reject %	0.57%	0.47%	1.55%	5.01%	0.00%	0.00%	1.41%	0.00%
Die Maintenance	0	0	0	0	0	0	0	0
Non-Specific	0	0	0	0	0	0	0	0
Non-Reject Scrap								
Trial Parts	90	90	0	81	0	0	1	0
Test Parts	196	88	0	103	0	0	45	0
Reject Description								
DC - Breakout (Broken Die)				37				
DC - Broken Gate	1			30				
DC - Computer reject/Biscuit Size							7	
DC - Contamination (Grease/Oil)				1				
DC - Dimensional (All dimensional except pin size and or depth/height)				135				
DC - Dropped Parts								
DC - Failed Leak Test				292				
DC - Flatness/Bent Parts				91			26	
DC - Flow Lines	70			102				
DC - Galling/Drags				2				
DC - Hard Spot				3				
DC - Hit Damage/Dent/Scratch/Nick		1		16				
DC - Lamination				1				
DC - NCU - Non Clean Up				2			8	
DC - NG Condition (DC)				20				
DC - No Good Date Pin	75							
DC - Over Grind				4				
DC - Porosity	7	3		74				
DC - Robot Dropping Parts	20							
DC - Surface Void (not including caused by broken gate)	7	4		21				
DC - Test Part	196	88		103			45	
DC - Trim Damage		1		3				
MS - Chatter			388	10			62	
MS - Cycle Stop	3	4		190				
MS - Dimensional (All dimensional except pin size and or depth/height)				77				
MS - Dropped	2	1		3				
MS - Flash In Bolt Hole			2					
MS - High Pin Pressure	27	89						

MS - Hit Damage/Dent/Scratch/Nick				32			1	
MS - Holesize				102			7	
MS - Low Pin Pressure	50	21						
MS - Machine Trial	90	90		81			1	
MS - Misset				1				
MS - Missing Bolt				125				
MS - NCU - Non Clean Up				18			33	
MS - NG Condition (MS)								
MS - Oil Hole No Good	60	2						
MS - Returned in empty dunnage								
MS - Skipped Proccess				2				
MS - Surface Roughness				1				
MS - Thickness							2	
MS - Tool Break				5				
MS - Tool Mark				10				
MS - Unidentified Part				2			2	
PC - Returned in empty dunnage								
TS - Flaking				1				
TS - Hit Damage/Dent/Scratch/Nick				1				

Reject Summary	Case comp Intermediate Dual - 680	Cover Inverter Single - 681	Cover Inverter Dual - 682	Inner Housing - 683	66V Fuel Pump - 686			
Total Rejects	0	0	0	0	0	0	0	
Die Cast Production	0	0	0	0	861	0	0	
Reject	0	0	0	0	0	0	0	
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	
Trim Shop Production	0	0	0	0	0	0	0	
Reject	0	0	0	0	0	0	0	
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	
Machine Shop Production	0	0	0	0	0	0	0	
Reject	0	0	0	0	0	0	0	
Reject %	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	
Die Maintenance	0	0	0	0	0	0	0	
Non-Specific	0	0	0	0	0	0	0	
Non-Reject Scrap								
Trial Parts	0	0	0	0	0	0	0	
Test Parts	0	0	0	0	4	0	0	
Reject Description								
DC - Test Part					4			

5A2	
Total Good Pcs	28,521
Total Reject	213
Scrap %	0.74%
Top Three Rejects %	
6MD Intake Manifold - 674	1.41%
6FB Holder Comp, No 1 Cam R - 644	0.78%
6FB Holder Comp, Oil Pass FRDC - 645	0.13%

5GO	
Total Good Pcs	50,720
Total Reject	44
Scrap %	0.09%
Top Three Rejects %	
5GO R/S #3 DC - 580	0.11%
5GO R/S #2 DC - 579	0.10%
5GO R/S #1 DC - 578	0.08%

6B2	
Total Good Pcs	210
Total Reject	28
Scrap %	11.76%
Top Three Rejects %	
6B2 HOLDER COMP NO5 R/S (DC) - 629	11.76%

DieCastBld1	
Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

DieCastBld2	
Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

DieCastBld3	
Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

DSI	
Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

MachineShop4	
--------------	--

Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

Madison Tool Die	
Total Good Pcs	7,404
Total Reject	980
Scrap %	11.69%
Top Three Rejects %	
R70 Case Oil Seal - 166	11.69%

MS Block2	
Total Good Pcs	28,949
Total Reject	87
Scrap %	0.30%
Top Three Rejects %	
6VJ Fuel Pump - 638	0.30%

NKP	
Total Good Pcs	0
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

OIL PANS	
Total Good Pcs	39,224
Total Reject	886
Scrap %	2.21%
Top Three Rejects %	
6MA Oil Pan (69F Finished) - 664	5.01%
RNA Oil Pan - 470	2.13%
64A Oil Pan - 648	1.38%

RPY	
Total Good Pcs	209,911
Total Reject	721
Scrap %	0.34%
Top Three Rejects %	
RPY Holder Comp No 5 Rkr Shaft - 139	100.00%
5BAA Holder Comp #5 R/S - 140	4.09%
RPY Holder Comp No 1 Ex Cam - 125	1.32%

RW	
Total Good Pcs	3,545
Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

SJ Precision	
Total Good Pcs	1,500

Total Reject	0
Scrap %	0.00%
Top Three Rejects %	

SMALL PARTS	
Total Good Pcs	401,326
Total Reject	1,305
Scrap %	0.32%
Top Three Rejects %	
6MAA HOLDCOMP SET (AEP) - 662	1.55%
6MAA HOLDCOMP NO4 EXHAUST (DC) - 660	0.57%
6MAA HOLDCOMP NO3 EXHAUST (DC) - 659	0.53%