



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 4

Lab# 2136

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Facility Name: *Wynnwood @ Freedom Road*
Address: *501 Cranberry Pointe Lane*
Cranberry, PA 16066

Sample Collection

Date: 8/25/26
Time: 12:50 PM
Method: Grab

Matrix: *Recreational Water*

Sample Final Analysis

Date: 8/28/26
Time: 12:00 PM
Analyst: AS

Source Type: *Pool*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	8/26/26	11:30 AM	AS	SM 9222G
Total coliforms:	0/100mls	2/100mls	8/26/26	11:30 AM	AS	SM 9222B
Standard plate count:	0/ml	200/ml	8/25/26	6:00 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.0 SU	7.2 - 7.8 SU	8/25/26	12:50 PM	EG	DPD
Chlorine:	5.0 mg/l	1.0 - 5.0 mg/l	8/25/26	12:50 PM	EG	DPD
Turbidity:	1 NTU	1 - 2 NTU	8/25/26	12:50 PM	EG	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor