



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

EOP-3

Lab# 2760

Customer

Facility Name: Idlewild and SoakZone

Address: 2574 Rt 30 E
Ligonier, PA 15656

Matrix: Recreational Water

Source Type: Splash Pool

Sample Collection

Date: 5/20/26

Time: 12:00 PM

Method: Grab

Sample Final Analysis

Date: 5/21/26

Time: 5:00 PM

Analyst: AS

Laboratory Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	5/20/26	4:50 PM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/20/26	4:50 PM	SL	SM 9222B
Standard plate count:	0/ml	200/ml	5/20/26	3:12 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	5/20/26	12:00 PM	EG	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	5/20/26	12:00 PM	EG	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/20/26	12:00 PM	EG	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor